While making up FMC wash tool to the bottom of a stand of d	rill pipe.The driller was attempting to torque .up same with top drive and manual tongs