

Its made up of a number of stamping which are slotted to receive the windings. the stator carries a 3 phase winding and is fed from a 3 phase supply. it is wound for a definite number of poles  $p=2n$  ; where  $n$  is number a stator slots/pole/phase. the exact number of poles being determined by the requirements of speed.