

o Dislocation motion requires the successive bumping of a half plane of atoms (from left to right). Most contain some dislocations that were introduced during solidification, plastic deformations, and rapid cooling (thermal stresses). o Bonds across the slipping planes are broken and remade in succession. The (plastic) permanent deformation of most crystalline materials is by dislocation movement.