

This happens because the current in the coil generates sufficient magnetic flux to attract the armature. Reset is manual and rapid.