

It was determined that the fire most likely started from an electrical arcing event that occurred above the ceiling on the right side of the cockpit near the cockpit rear wall. The arcing event ignited the flammable cover material on nearby metallized polyethylene terephthalate (MPET) covering on the thermal acoustic insulation blankets.