The diagram shown is a sketch of a relief valve. The pressure is applied directly on the spring seat as shown As the pressure applied, the force exerted on each bolt is 1000 N. The jomt stiffness constant is .36%