

Equipment: In some instances, the sealing temperature of the plastic sealing machine exceeded the set parameters, potentially leading to non-conforming sealing quality