

At the beginning of the implementation you might have a large number of product/process characteristics being monitored and controlled, since control charts can give you immediate feedback. If later on some control charts along the process are found to be unnecessary due to stabilization of the characteristic monitored, control charts at that area can be removed.