

Luminance is defined as the luminance intensity per unit projected area of either a surface source of light or reflecting surface as is denoted by (L) where  $\{ L=I/A \cos \theta \}$ . Luminance is called light level and is measured in foot-candles (fact