

Locate and ensure you are familiar with all machine operations and controls. Adjust the spindle speed to suit drill or cutter diameter. Check workspaces and walkways to ensure no slip/trip hazards are present.