

Additionally, disturbance during sampling can change the soil structure and moisture content, leading. 1
to erroneous density measurements. If the dimensions of the cutter are not measured accurately or if
.there is a calibration issue with the weighing scale, the calculated density may be incorrect. 2