

While making up FMC wash tool to the bottom of a stand of drill pipe. The driller was attempting to torque up same with top drive and manual tongs.