

The isoelectrics represent lines of constant stress and are analogous to contour lines on a topographic map. It is necessary to calibrate the coating.