

In this experiment, we have done many things in two activities. The first one was system analysis; to determine the value of (K) to make an overshoot of 20% for the temperature control system which was given in the activity. The second activity was improving performance with PID, it's like the complete part (of the first activity. – Change the settling time of 10 seconds or better (less