

The characteristics of this production system are: 1. High variety of products and low volume. 2. Use of general-purpose machines and facilities. 3. Highly skilled operators who can take up each job as a challenge because of uniqueness. 4. Large inventory of materials, tools, parts