

The diagram shown is a sketch of a relief valve. The pressure is applied directly on the spring seat as shown. As the pressure is applied, the force exerted on each bolt is 1000 N. The joint stiffness constant is 36%.