

?Two halves of the mold must be tightly closed before the molten material is injected into the mold. The clamping of the mold is operated hydraulically, which it pushes the moving half of the mold towards the fixed part to make an air tight chamber.???